HAER No. PA-146

Bethlehem Union Station Bethlehem Lehigh Valley RR and Reading RR tracks Bethlehem Northampton County Pennsylvania

HAER PA 48-POETH, 15-

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Engineering Record
National Park Service
Department of the Interior
Washington, DC 20013-7127

HAER PA, 48-BETH, 15-

## HISTORIC AMERICAN ENGINEERING RECORD

## BETHLEHEM UNION STATION

HAER No. PA-146

Location:

Between the Lehigh Valley Railroad and Reading Railroad tracks, adjacent to Second Street ramp's Hill-to-Hill Bridge, Bethlehem, Pennsylvania.

Description:

Two story brick over stel frame with a full height central waiting room, capped with the remnants of a stained glass skylight, glazed tile walls and shops around the perimeter.

History:

Built in 1924 between the Lehigh Valley Railroad and the Reading Line, this building stands on the site of an earlier union station. The building is vacant today and a victim of severe water damage. Plaster has fallen away from the ceiling and walls, destroying the station's frescoes.

Source:

Railway Review 12 July 1924, pp. 55-56.

Historian:

Peter H. Stott and Duncan Hay, HAER Inventory, 1979.